
Wear Plate

Sintered Blank Type

Slide Components

SOXB









〈Material〉SO#220 Hatched Area Sintered Thickness 1.2 mm or more T=10 1045 (S45C) (base plate) T≧20 SS400 (base plate)

Catalog No.	w	L	Т
	75		
	100		10
	125		10
	150	590	
SOXB	75	330	
	100		20
	125		
	150		
	100	320	25



Catalog No.	W]-	L]-[Т
SOXB	100	_	320	_	25

■For Operation

- · Cut or drill the plate as required.
- · When the thickness is adjusted, machine the back surface.
- · Apply grease for initial lubrication before operation.

Recommended Bolt

