
| Catalog No. | W | L |
|-------------|------|------|
| EMS | 1000 | 1000 |
| EIVIS | | 2000 |




■For Operation

- This plate has emboss dimples.
 Use the plate at the angle of 12° or more.
- Spot weld this plate on a normal scrap chute for use.
- The welding interval is approximately 150 to 200 mm.



Stopper For Scrap Chute

FOR SCRAP CHUTE




■ Chain Set for Chute Fixing

| t | Number of Links | Catalog No. | L |
|---|-----------------|-------------|-----|
| | 7 | | 200 |
| 5 | 10 | CHNS | 300 |
| | 15 | | 500 |

Order Catalog No. L
CHNS 200

The joint bracket (3) is to be welded after fine adjustments are done.





The chain-set described as CHNS is to be fixed onto the lower die and the scrap chute.